

使用说明书

Operate Manual

目录 CATALOGUE

[一]使用须知	01
[二]注意事项	02
[三]功能描述	03
[四]技术参数	04
[五]外观结构介绍	05
[六]测量流程图	06
[七]软件界面介绍	08
7.1 功能介绍	08
7.2 登陆	10
7.3 向导	13
7.4 校准	19
7.5 测量	22
7.6 设置	24
7.7 数据浏览	31

7.8 个人中心	36
7.9 关于	37
7.10 日志	38
7.11 更新	39
[八]测量界面介绍	40
8.1 雾度/透过率/清晰度	40
8.2 雾度/透过率	41
8.3 雾度	42
8.4 透过率	43
8.5 清晰度	44
8.6 色差	45
8.7 数据	51
8.8 图形	52
8.9 同色异谱	58
8.10 液体色度	59
[九]参数介绍	60
[十]异常处理分析	64
[十一]附件	65
[十二]公司声明	67

使用须知

- 1、本机是一台设计用于测定塑料、薄膜、玻璃制品、LCD面板等透明、半透明平行平面材料的雾度、总透光率、光谱透射性能的仪器。
- 2、本机广泛应用于实验室、工厂、或现场操作，足以在几乎所有应用领域的质量控制中实现最佳的雾度、颜色测量。
- 3、限制性保修的时间段是自购买本仪器开始起（时间：如一年）的时间。如果您的仪器需要服务，请将仪器带到当地的销售部联系我们来进行维修。
- 4、为了避免仪器精度受影响，请不要将仪器私自拆开。如果由于私自拆卸机器或不正确的使用而导致仪器损坏，请用户自行负责。

注意事项

- 1、本机属精密仪器，不能承受跌落导致的碰撞，使用时请放置于相对平整的地方。
- 2、本机不能防潮或抗潮，受潮或液体溅入易损坏本机。
- 3、本机的屏幕是由玻璃制成，受到异常外力或锐器的作用易损坏。
- 4、本公司建议使用原配电源适配器。
- 5、为保障本机正常工作，请不要在过冷或过热的地方存贮和使用，也勿将本机放置在潮湿或阳光长期直射的地方，更不要在强震等恶劣的环境中使用本机，以免发生意外。
- 6、本机是精密仪器，使用时请避开强电磁干扰。
- 7、为保证测量准确，测试时请保持仪器平稳，不要摇晃。
- 8、本机属精密仪器，使用完毕请将仪器关机保管。
- 9、请将仪器存放在干燥的地方。
- 10、禁止对积分球内部进行清洁。
- 11、如果仪器发生故障，请不要尝试自行修理，我们的客户服务部门会快速的为客户提供帮助。

12、本机及说明书如有进一步改进或补充，恕不另行通知。如有疑问，敬请垂询本公司。



功能描述

- 1、设计符合以下测试标准：ASTM D1003/D1044,ISO 13468/ISO 14782,JIS K 7105,JIS K 7361,JIS K 7136,GB/T 2410-2008,JJF 1303-2011；
- 2、满足CIE-A、CIE-C、CIE-D65三种标准照明光源下的雾度、全透过率与清晰度测量；
- 3、满足补偿法测试，可提供更准确的测试结果；
- 4、拥有开放式的测量区域，可以满足任意大小的样品测量；
- 5、采用7.0寸电容触摸屏，Android操作系统，拥有良好的人机交互界面；
- 6、提供专业的雾度以及透过率的测量分析软件，可以满足用户对测试数据的分析以及管理；

技术参数


符合标准	ASTM D1003/D1044,ISO13468/ISO14782,JIS K 7105,JIS K 7361,JIS K 7136,GB/T 2410-08,CIE No.15,ISO 7724/1,ASTM E1164,DIN 5033 Teil7,JIS Z8722 Condition c
光路结构	0/d
光源	雾度/透过率: CIE-A,CIE-C,CIE-D65 色度指标: A,C,D50,D55,D65,D75,F1,F2,F3,F4,F5,F6,F7,F8,F9,F10,F11,F12,CMF, U30,DLF,NBF,TL83,TL84
光谱响应	CIE光谱函数Y/V (λ)
测量参数	雾度 (HAZE),透过率 (T),光谱透过率,清晰度 CIE Lab,LCh,CIE Luv,XYZ,Yxy,Hunter Lab,MunsellMI,CMYK,白度WI(ASTM E313-00, ASTM E313-73,CIE/ISO,Hunter,Taube Berger Stensby), 黄度YI(ASTM D1925,AST M E313-00,ASTM E313-73), Tint(ASTM E313-00),同色异谱指数Milm, APHA,Pt -Co (铂钴指数),Gardner(加德纳指数),色差 (ΔE*ab,ΔE*CH,ΔE*uv,ΔE*cmc(2:1), ΔE*cmc(1:1),ΔE*94,ΔE*00)
波长范围	400-700nm
波长间隔	10nm
量程	0-100%
分辨率	0.01单位
重复性	雾度 < 10%，重复性≤0.05%；雾度 ≥ 10%，重复性≤0.1%;透光率≤0.1%;清晰度≤0.1%
照明/样品孔径尺寸	18mm/25.4mm
样品大小	厚度≤145mm
显示	7英寸电容触摸屏
存储数据	20000个数值
接口	USB接口
电源	220V (自带电源线)
工作温度	0~45℃，相对湿度80%或更低 (在35℃下) ，无水气凝结
储藏温度	-25℃~55℃，相对湿度80%或更低 (在35℃下) ，无水气凝结
体积	长X宽X高: 598mmX247mmX366mm
标配	PC管理软件 (Haze QC)
选配	测量夹具、雾度标准片、5mm/7mm/10mm□径板、40*10比色皿

外观结构介绍




- | | | | |
|---------|--------|--------|---------|
| ① 显示屏 | ② 出光口 | ③ 补偿口 | ④ 测试口 |
| ⑤ USB接口 | ⑥ 电源开关 | ⑦ 电源接口 | ⑧ 光源更换口 |


测量流程图




0%校准、100%校准、清晰度校准




标样测量、试样测量



检查测量结果



保存、不保存测量结果



完成

软件界面介绍

[功能介绍]

A-1

主界面

软件分为8个模块，分别是：校准、测量、设置、数据浏览、个人中心、关于、日志、更新。



A-2

标题栏

标题栏从左到右分别为:主页按钮、测量模式、光源和观察角。



[登录]

登录分为本地登录和网络登录两种方式。勾选记住密码，下次开机时将会自动输入账户与密码，勾选自动登录下次开机将跳过登录页面，直接进入软件。

B-1

本地登录账户为：admin，密码默认为仪器序列号（登录后可以在个人中心进行修改）。
例如仪器序列号是：C81118C0128，则在登录密码处输入C81118C0128即可。

Language 简体中文

Wifi设置

登录

注册

本地登录

admin

.....

☒ 记住密码 ☐ 自动登录

登录

忘记密码?

B-1

B-2

网络登录

网络登录需要连接网络，点击注册进行账户注册，可选择邮箱或手机号进行注册。注册完成后可以使用注册的账户进行登录。使用网络登录可以将存储的数据上传到云端，可在windows端进行数据管理。

Language 简体中文

Wifi设置

登录

注册

请输入账号	请输入公司名称
请输入密码	请输入公司地址
请确定密码	请输入联系人姓名
请输入手机号码	请输入邮箱
请输入验证码	获取验证码
注册	

B-2

[向导]

C

第一次登录软件或恢复出厂后重新登录后，会进入仪器使用向导，可以根据向导对仪器进行设置。



C-1

仪器设置

退出

雾度测量标准

☒ ASTM

☐ ISO

系统设置

屏幕背光

选择语言

简体中文

恢复出厂

屏幕旋转

Wifi设置

时区设置

上一步

下一步

1/5

C-2

参数设置

退出

光源&视角 (第二光源用于计算同色异谱)

第一光...

C

2°

第二光源

A

2°

CMC(l:c)

l

2.0

c

1.0

CIE94

KL

1.0

KC

1.0

KH

1.0

CIE 2000

KL

1.0

KC

1.0

KH

1.0

2/5

上一步

下一步

C-3

容差设置

退出

雾度/透过率 CIE LAB&LCH Hunter Lab CIEDE2000 CIE LUV CMC(l:c)&CIE94 液体色度 温度&湿度

雾度/透过率

		大于正值	小于负值	两者之间
dh(雾度) : ±	<input type="text" value="2.0"/>	不合格	不合格	合格
dt(透过率) : ±	<input type="text" value="2.0"/>	不合格	不合格	合格
dC : ±	<input type="text" value="2.0"/>	不合格	不合格	合格

3/5

上一步

下一步

C-4

其他设置

退出

平均设置

☒ 单次测量 ☐ 平均测量

保存设置

☒ 手动保存 ☐ 自动保存

命名规则

标样	<input type="text" value="标样"/>	+	<input checked="" type="checkbox"/> 序号	+	<input type="checkbox"/> 日期
试样	<input type="text" value="试样"/>	+	<input checked="" type="checkbox"/> 序号	+	<input type="checkbox"/> 日期


上一步

下一步

模板选择

- 雾度/总透过率/清晰度
- 雾度/透过率
- 雾度
- 透过率
- 清晰度
- 色差
- 数据
- 图形
- 同色异谱
- 液体色度

5/5



上一步

完成

C-6

[校准]

D-1

0%校准

根据软件的提示进行0%校准。ASTM模式时，请将补偿口（comp-port）用补偿口盖盖上；ISO模式时，请保持补偿口（comp-port）处于打开状态。
该页面可以对校准有时间进行设置，默认校准有效时间为8小时。



D-1

100%校准

根据软件的提示进行100%校准。



校准

ASTM C/2°

校准有效时间

8小时

▼



第二步

100%

请保持haze-port对准空气，并点击测量键进行校准

仪器0%校准成功

校准

清晰度校准

根据软件的提示进行清晰度校准。

 校准

ASTM C/2°

校准有效时间 8小时



第三步

清晰度校准

请将校准片放置clarity-port，并点击校准键进行清晰度校准

仪器100%校准成功

校准


[测量]

测量分为三种模式：标样测量、试样测量以及其他测量模式（同色异谱、液体色度）。

E-1

标样测量

在主页点击测量进入标样测量界面，在样品放置完成后，点击屏幕右下角测量按钮，屏幕上显示测量数据，测量按钮恢复可按压状态，表示测量完成。



试样测量

在标样测量界面，点击界面中的试样测量，切换到试样测量界面，同样在样品放置完成后，点击屏幕右下角测量按钮，进行试样数据测量。



[设置]

设置界面可以对仪器测量方式、数据计算参数、容差、软件显示、保存方式、命名规则、平均等进行配置，进行修改后需要点击“应用”按钮。

F-1

仪器设置

仪器设置分为6个区域：

- 1、雾度测量模式：可设置ASTM模式或ISO模式；
- 2、系统设置：可以设置屏幕背光以及语言切换；
- 3、恢复出厂：软件配置恢复到初始状态
- 4、屏幕旋转：点击屏幕旋转屏幕显色反向将旋转180° ；
- 5、wifi设置：可以选择WiFi并登陆；
- 6、时区设置：不同国家的时间显示，联网可自动同步时间。



F-2

参数设置

参数设置可对数据计算进行配置

1、光源&角度：可以设置计算数据的光源与角度，第一光源与角度为所有模式下的计算数据，第二光源只用于计算同色异谱（注：相近色查找显示数据固定为D65/10°）

- 2、CMC(l:c):可以设置CMC色差公式的l:c系数；
- 3、CIE 94:可以设置CIE94色差公式的KL、KC、KH系数；
- 4、CIE 2000:可以设置CIE2000色差公式的KL、KC、KH系数；

设置

ASTM C/2°

仪器

参数

容差

显示

其他

向导

应用

光源&视角 (第二光源用于计算同色异谱)

第一光...

C

2°

第二光源

A

2°

CMC(l:c)

l

2.0

c

1.0

CIE94

KL

1.0

KC

1.0

KH

1.0

CIE 2000

KL

1.0

KC

1.0

KH

1.0

F-2

容差设置

容差用来判断测量数据是否合格的依据，当测量数据超过容差范围时将提示数据不合格，当测量数据小于等于容差时将提示数据合格。

该界面下可以设置不同色差公式以及模式的容差。（其中CIE LAB可以用户自定义提示语言）



显示设置

显示设置可以设置“测量页面”下显示的内容。分为如下几个：

- 1、雾度/透过率/清晰度：同时显示雾度、总透过率以及清晰度参数；
- 2、雾度/透过率：同时显示雾度、总透过率参数
- 3、雾度：仅显示雾度参数；
- 4、透过率：仅显示总透过率参数；
- 5、清晰度：仅显示清晰度参数；
- 5、色差：CIELABCH、CIEDE2000、CIE94、CMC、HunterLab；
- 6、数据：该模式可以显示除了雾度与遮盖力以外该仪器所有能够测量的参数；
- 7、图像：CIE LAB图、Yxy图、Luv图、反射/透过率图、K/S曲线图、吸光度曲线图；
- 9、同色异谱：测量同色异谱参数；
- 10、液体色度：测量saybolt、ASTM color、铂钴色度、Gander color；



F-6

其他设置

- 1、平均设置窗口可以设置单次测量还是平均测量；
- 2、保存设置窗口可以设置手动保存还是自动保存；
- 3、命名规则窗口可以设置标样试样保存时候的名字规则。



F-6

[数据浏览]

G

- 1、页面左边显示的是标样数据列表，右边是标样下的试样数据列表；
- 2、页面左边上面有一个搜索框，点击可以搜索标样数据；
- 3、点击其中一条标样后，可以在界面右边看到标样数据下的试样数据详细信息；
- 4、长按标样或试样可以选择调出、修改、删除当前选择、删除全部；
- 5、点击标样进入试样详细信息界面可以搜索当前标样下的试样，可进行导出当前显示数据；
- 6、点击参数编辑弹出参数编辑窗口，可以在这里面选择在数据界面显示的参数。

标样搜索框

标样数据列表

标样搜索

标样0002

标样0001

参数编辑

	名称	L*	a*	b*	dE*ab	dE*ab
标样	标样0002	82.01	1.57	7.14	--	--

试样搜索

名称

查找

导出

导出全部

ASTM C/2°

G-1

数据浏览

ASTM C/2°

标样搜索

标样0002

标样0001

参数编辑

名称	L*	a*	b*	dE*ab	dE*ab
标样	标样0001	81.95	1.55	7.24	--
0	试样0001	81.98	1.54	7.19	0.05

试样搜索

名称

查找

导出

导出全部

试样数据列表

可进行导出当前
显示数据和导出
全部数据

G-2

数据浏览

ASTM C/2°

标样搜索

标样0002

标样0001

参数编辑

	名称	L*	a*	b*	dE*ab	dE*ab
标样	标样0001	81.95	1.55	7.24	--	--
0	试样0001	81.98	1.54	7.19	0.05	合格

调出为标样

修改

删除选中

删除全部

试样搜索

名称

查找

导出

导出全部



[个人中心]

H-1

个人中心界面可以修改账户密码，注销当前账号。

个人中心

ASTM C/2°

账号: admin

公司名称

公司地址

联系人姓名

邮箱

修改账户密码

原密码

新密码

确认密码

确定

注销

H-1

[关于]

I-1

关于界面可以查看仪器的信息，比如软件版本，仪器版本，仪器序列号，仪器型号等等。



I-1

[日志]

J-1

日志界面可以看到仪器的登陆信息，校准信息，仪器错误信息等。

日志		ASTM C/2°
2016-01-01 09:47:53.7	仪器100%校准成功	
2016-01-01 09:47:23.5	仪器0%校准成功	
2016-01-01 09:43:50.5	登录账户 admin	
2016-01-01 09:41:36.9	仪器100%校准成功	
2016-01-01 09:41:25.6	仪器0%校准成功	
2016-01-01 09:40:18.0	仪器自检结果:0	
2016-01-01 09:26:13.9	仪器自检结果:0	
2016-01-01 08:06:05.6	仪器自检结果:0	
2016-01-01 08:01:30.8	仪器自检结果:0	
2016-01-01 08:00:34.8	仪器自检结果:0	
2016-01-01 08:08:48.4	仪器100%校准成功	
2016-01-01 08:08:35.9	仪器0%校准成功	
2016-01-01 08:03:49.7	登录账户 admin	

J-1

[更新]

K-1

联网情况下，可以点击更新检测是否有新软件，获取最新软件。




测量界面介绍

[雾度/透过率/清晰度]

L-1

在这个界面，可以同时显示雾度、总透过率、清晰度和透过率曲线（%），通过对比标样试样计算出雾度、总透过率和清晰度的差值，同时通过设定的容差自动判断样品是否合格。



L-1

[雾度/透过率]

M-1

在这个界面，可以同时显示雾度、总透过率和透过率曲线（%），通过对比标样试样计算出雾度和总透过率的差值，同时通过设定的容差自动判断样品是否合格。



M-1

[雾度]

M-1

在这个界面，仅显示雾度和透过率曲线（ % ），通过对比标样试样计算出雾度的差值，同时通过设定的容差自动判断样品是否合格。




M-1

[透过率]

N-1

在这个界面，仅显示总透过率和透过率曲线（ % ），通过对比标样试样计算出总透过率的差值，同时通过设定的容差自动判断样品是否合格。



[清晰度]

0-1

在这个界面，仅显示清晰度，通过对比标样试样计算出清晰度的差值，同时通过设定的容差自动判断样品是否合格。

ASTM C/2°

标样测量 -- 标样0003

试样测量 -- 试样0001

清晰度	
标样	76.79
试样	76.77
差值	-0.02
判断	合格

设置

保存

测量

0-1

[色差]

P-1

CIELABCH

在这个界面可以测量样品颜色的 L^* 、 a^* 、 b^* 、 c^* 、 h 值，通过对比标样试样计算显示出 dL^* 、 da^* 、 db^* 、 dc^* 、 dH^* ，以及 dE^*_{ab} ，同时通过设定的容差自动判断样品是否合格。

ASTM C/2°

标样测量 --- 标样0003

试样测量 --- 试样0001

标样

$L^* = 82.01$
 $a^* = 1.49$
 $b^* = 7.36$
 $c^* = 7.50$
 $h = 78.56$

试样

$L^* = 82.00$
 $a^* = 1.51$
 $b^* = 7.34$
 $c^* = 7.49$
 $h = 78.40$

$dL^* = -0.01$ 合格
 $da^* = 0.02$ 合格
 $db^* = -0.01$ 合格
 $dc^* = -0.01$ 合格
 $dH^* = -0.02$ 合格

dE^{*ab}
0.02 合格

设置

保存

测量

P-2

CIEDE2000

在这个界面可以测量样品颜色的L*、a*、b*、c*、h值，通过对比标样试样计算显示出dL'、dC'、dH'，以及dE*2000，同时通过设定的容差自动判断样品是否合格。



P-3

CIE94

在这个界面可以测量样品颜色的L*、a*、b*、c*、h值，通过对比标样试样计算显示出dL*、da*、db*、dc*、dH*，以及dE*94，同时通过设定的容差自动判断样品是否合格。



P-4

CMC

在这个界面可以测量样品颜色的L*、a*、b*、c*、h值，通过对比标样试样计算显示出dL*、da*、db*、dc*、dH*，以及dEcmc(l:c)，同时通过设定的容差自动判断样品是否合格。

ASTM C/2°

标样测量 — 标样0003

试样测量 — 试样0001

标样

L* = 82.03
a* = 1.46
b* = 7.30
c* = 7.45
h = 78.66

试样

L* = 82.00
a* = 1.54
b* = 7.25
c* = 7.41
h = 78.04

dL* = -0.04 合格
da* = 0.07 合格
db* = -0.05 合格
dc* = -0.03 合格
dH* = -0.08 合格

dEcmc(2.0:1.0)
0.13 合格

设置

保存

测量

P-5

Hunter Lab

在这个界面可以测量样品颜色的Hunter L、Hunter a、Hunter b值，通过对比标样试样计算显示出dHunter L、dHunter a、dHunter b，以及dEab，同时通过设定的容差自动判断数据是否合格。

ASTM C/2°

标样测量 --- 标样0003

试样测量 --- 试样0001

标样

(Hunter)

L = 77.67
a = 1.48
b = 6.70

试样

(Hunter)

L = 77.66
a = 1.48
b = 6.68

dL = -0.01 合格
da = -0.01 合格
db = -0.01 合格

dEab
0.02 合格

设置

保存

测量

P-5

50

[数据]

Q-1

- 1、在数据界面可以点击参数编辑来选择你想要看的参数；
- 2、通过测量标样，然后测量试样来查看样品的参数差值；
- 3、点击数据可以选中，长按数据可以对数据进行删除，重命名等操作。

ASTM C/2°						
标样测量 试样测量						
参数编辑	名称	L*	a*	b*	dE*ab	dE*ab判
标样	标样0003	82.02	1.53	7.23	--	--
1	试样0001	82.02	1.48	7.27	0.06	合格


Q-1

[图形]

R-1

CIELAB


在该界面可以测量样品的L*、a*、b*值，同时用该样品的a*、b*值在CIELAB图上描点并显示数据的L*、a*、b*值。



R-2

Yxy

在该界面可以测量样品的Y、x、y值，同时用该样品的x、y值在Yxy图上描点并显示数据的Y、x、y值。




R-2

R-3

Luv

在该界面可以测量样品的 L^* 、 u^* 、 v^* 值，同时用该样品的 u' 、 v' 值在Luv图上描点并显示数据的 L^* 、 u^* 、 v^* 值。




R-3

R-4

k/s曲线


在该界面可以测量样品的k/s值，同时显示360–780nm下的K/S曲线图。



R-4


透过率曲线

在该界面可以测量样品的透过率值，同时可以显示360–780nm下的透过率曲线图。



吸光度曲线


在该界面可以测量样品的吸光度值，同时可以显示360–780nm下的吸光度曲线图。



[同色异谱]

S-1

界面左边是测量样品使用第一光源/角度计算出来的数值，右边是测量样品使用第二光源/角度计算出来的数值，界面中见下面的同色异谱值是样品在两光源角度下计算出来的同色异谱数值。



S-1

[液体色度]

T-1

界面左边比色皿光程是测量不同参数推荐的比色皿光程大小(例如您想测量saybolt参数，这个时候推荐的比色皿光程大小是50mm)，右边是参数的数值，以及是否合格判断。

ASTM C/2°

标样测量 — 标样0003

试样测量 — 试样0001

比色皿光程	参数	标样	试样	差值	判断
10mm	Pt-Co/Hazen/APHA	373.23	378.31	5.08	不合格
10mm	Gardner Color	1.96	1.98	0.02	合格
50mm	Saybolt	16	16	0	合格
33mm	ASTM Color	0.9	0.9	0.0	合格

设置

保存

测量

T-1

参数介绍


雾度

漫散射会降低物体的成像质量。材料内部细小的颗粒或样品表面会引起散射，散射光会散射到不同的角度且每个角度的光密度都很小，这会导致对比度的降低，样品会形成如牛奶或云雾状的外观，这一现象称为雾度。

透明度评估条件


透明产品外观具有光泽、颜色和透明度等特性。透明度尤为重要，其评估条件为：透光率，雾度等。透过率是全部透射的光与入射光的比率。它会随材料表面对光的反射和吸收而降低。根据ASTM D1003标准，雾度是超出 2.5° 散射的入射光所在全部入射光的百分比。

测量原理




一束平行光照射到样品后进入一个积分球体内。光线在球体内壁白色涂层上进行散射，通过感应器进行测量，球体右侧光阱出口关闭时测量全透过率。右侧光阱出口开启时测量雾度。

补偿法



上图为不采用补偿法测量透过率，在两次测量中，由于积分球的面积不相同，导致积分球效率不同，从而对测量结果的准确性产生一定影响。




上图为采用补偿法测量透过率，在积分球上增加一个补偿口，第一次测量样品放置于补偿口处，第二次测量样品放置于测量口，同时补偿口处于打开状态，两次测量过程积分球面积完全一致，保证积分球效率一直，从而使测量结果更准确。

异常处理分析


异常情况	分析	处理方法
1、仪器无法开机	电源连接可能异常	检查电源接口处是否接触良好，并插好电源
2、开机后不能进入主程序	开机校准过程可能异常	重新按照要求进行校准保证校准顺利通过
3、测量结果报错	容差设置可能异常	检查容差设置并调整
4、测试数值异常	1、样品与测量口贴合紧密与否 2、样品表面损伤是否较大	1、检查样品与测量口的贴合情况，保证紧密贴合 2、检查样品表面情况，保证样品是完好的对测量没有影响的

附件


标配件




外部电源适配器




USB数据线



数据管理软件光盘




补偿口盖子




0校准遮光盖

选配件



固体样品夹具



比色皿夹具

公司声明

- 本公司向用户承诺，本产品保修期限为购买之日起的三年内有效，正常使用情况下非人为造成的故障问题，本公司将负责给予免费维修，超过保修期或人为因素导致的故障，本公司将提供维护，将收取维修材料及相关费用。
- 本公司对于第三者因使用本产品引起的任何损失或索赔不负任何责任。
- 本公司对由于故障、维修、断电或更新软件造成的数据丢失而导致的任何损害或损失均不负任何责任。为防止重要数据的丢失，请务必对所有重要数据进行备份。
- 本产品中预置的所有作品之版权归本公司所有，受《中华人民共和国著作权法》保护。
- 我公司出售本产品的行为不代表向用户转让或授予与作品版权相关的任何权利。
- 本说明书所提到的产品规格及信息仅供参考，内容会随时更新，恕不另行通知。

Operation Manual

CATALOGUE

[I] Usage Notice-----	01	7.8 Personal center-----	37
[II] Precautions-----	02	7.9 About -----	38
[III] Functional description-----	03	7.10 Log -----	39
[IV] Technical Paramet -----	04	7.11 Update-----	40
[V] Introduction to appearance structure-----	05	[VIII] Introduction to the measurement interface-----	41
[VI] Measurement flow chart-----	06	8.1 Haze/transmittance/Clarity -----	42
[VII] Software interface introductio -----	08	8.2 Haze/transmittance -----	42
7.1 Features-----	08	8.3 Haze-----	43
7.2 Login-----	10	8.4 Transmittance -----	44
7.3 Guide-----	13	8.5 Clarity -----	45
7.4 Calibration-----	19	8.6 Color difference-----	46
7.5 Measure-----	22	8.7 Data -----	52
7.6 Set up -----	25	8.8 Figure -----	53
7.7 Data browsing -----	32	8.9 Metamerism-----	59
		8.10 Liquid-----	60
		[IX] Parameter introduction-----	61
		[X] Exception handling analysis-----	65
		[XI] Annex -----	66
		[XII] Company statement-----	68

Usage Notice

- 1、 This machine is an instrument designed to measure the haze, total light transmittance, and spectral transmittance of transparent, translucent parallel plane materials such as plastics, films, glass products, LCD panels, etc.
- 2、 This machine is widely used in laboratory, factory, or field operation, enough to achieve the best haze and color measurement in quality control in almost all application fields.
- 3、 The time period of the limited warranty is the time since the purchase of this instrument (time: such as one year). If your instrument needs service, please bring the instrument to the local sales department to contact us for repair.
In order to avoid affecting the accuracy of the instrument, please do not
- 4、 Disassemble the instrument without permission. If the instrument is damaged due to unauthorized disassembly of the machine or incorrect use, the user is responsible for it.

Precautions

- 1、 Put the instrument on the flat place carefully.
- 2、 The instrument is not moistureproof, please keep the instrument in the dry area.
- 3、 Large force, or sharp objects may damage the screen.
- 4、 It is recommended to use the original power adapter which comes with the instrument.
- 5、 To ensure the machine to work properly, please do not store, or use the instrument in places that are too hot or too cold; please do not put the machine in damp locations, or directly under sunlight. Do not use the instrument in severe environment such as strong shock or quake.
- 6、 Please avoid strong electromagnetic interference in usage.
- 7、 To ensure accurate measurement, please keep the instrument stable during the test and do not shake it.
- 8、 Instrument belongs to high precision instrument, please keep it well after usage.
- 9、 Do not clean the inside of the integrating sphere.
- 11、 If the instrument fails, please don't try to repair it by yourself, our customer service department will quickly help the customer.

- 12、 Any future update on the manual, we are not obliged to notify you.
If any questions, please contact us directly.



Functional description

- 1、 Color and Haze meter conforms to standards: GB/T 2410, ASTM D 1003, ISO 13468, ISO 14782 and GB/T 2410-2008,JJF 1303-2011.
- 2、 Color and Haze meter can provide haze and transmittance value under CIE-A, CIE-C and CIE-D65 light sources.
- 3、 Color and Haze meter contains compensation method which provides higher accuracy on test result.
- 4、 Open sample measurement area to make it can measure samples at any sizes.
- 5、 Haze meter adopts 7.0 inch capacitive touch screen and Android operating system for friendly interface.
- 6、 Haze, color and transmittance analysis software to meet customer's requirement on data analysis and management.

Technical Parameters



Standard	ASTM D1003/D1044,ISO13468/ISO14782,JIS K 7105,JIS K 7361,JIS K 7136,GB/T 2410-08,CIE No.15,ISO 7724/1,ASTM E1164,DIN 5033 Teil7,JIS Z8722 Condition c
Geometry	0/d
Light Source	Haze/ Transmittance: CIE-A,CIE-C,CIE-D65 Chromaticity Value: A,C,D50,D55,D65,D75,F1,F2,F3,F4,F5,F6,F7,F8,F9,F10,F11,F12,CMF, U30,DLF,NBF,TL83,TL84
Spectral Response	CIE Luminosity function Y/V(λ)
Measurement Parameter	HAZE,Transmittance (T),CIE Lab,LCh,CIE Luv,XYZ,Yxy,Spectral Transmittance,Clarity, Hunter Lab MunsellMI,CMYK,WI(ASTM E313-00,ASTM E313-73,CIE/ISO,Hunter, Taube Berger Stensby),YI(ASTM D1925,ASTM E313-00,ASTM E313-73), Tint(ASTM E313-00),Metamerism IndexMilm,APHA,Pt-Co,Gardner, Color difference (ΔE*ab, ΔE*CH, ΔE*uv, ΔE*cmc(2:1), ΔE*cmc(1:1), ΔE*94, ΔE*00)
Wavelength	400-700nm
Wavelength Interval	10nm
Measurement Range	0-100%
Haze Resolution	0.01unit
Haze Repeatability	≤0.1unit
Measurement Area/Sample Port	18mm/25.4mm
Sample Size	Thickness≤145mm
Display	7 inch capacitive touch screen
Memory	20000values
Interface	USB
Power	220V (with power cable)
Working Temperature	0~45℃, Relative humidity 80% or lower (35℃) no condensation
Storage Temperature	-25℃~55℃, Relative humidity 80% or lower (35℃) no condensation
Size	LxWxH: 598mmX247mmX366mm
Standard Accessory	PC software (Haze QC)
Optional	Measurement Fixture、Haze Standard Plate、5mm/7mm/10mmCaliber plate、40*10Cuvette

Appearance and structure




- ① Display Screen ② Light Exit Aperture ③ Compensation Aperture ④ Test Aperture
⑤ USB ⑥ Switch on-off ⑦ Power Interface ⑧ Light Source Exchange port


Measurement flow chart




0% Calibration, 100% Calibration, Clarity Calibration




Target Measure and Sample Measure



Check measurement results



Save/not save the test result



Finish


Software interface introduction

[Features]

A-1

Main Interface


The software is divided into 8 modules, namely: calibration, measurement, setting, data browsing, personal center, about, log, update.



A-2

Title

From left to right, the title bar is: home button, measurement mode, light source and viewing angle.



[Log In]

Login is divided into local login and network login. Check the Remember password, the account and password will be automatically entered when the next boot, check from The next time you start automatic login, you will skip the login page and go directly to the software.

B-1

The local login account is: admin, and the password is the instrument serial number by default (you can modify it in the personal center after login).For example, the instrument serial number is: C81118C0128, then enter C81118C0128 at the login password.

LanguageEnglish

Wifi Setting

LoginRegister

Local Login

admin

.....

☒ Keep Password

☐ Auto Login

Login

Forget Password?

B-1

Network Login

You need to connect to the Internet to log in to the Internet. Click Register to register your account. You can choose your email or mobile phone number to register. After the registration is completed, you can log in using the registered account. Use the network login to upload the stored data to the cloud, and perform data management on the windows.

LanguageEnglish

Wifi Setting

Login


Register

Account	Company Name
Password	Address
Confirm Password	Name
Cell Phone	Email
Input Code	Get Code
Register	

[Guide]

C

After logging into the software for the first time or re-login after restoring the factory, you will enter the instrument user guide, and you can set the instrument according to the guide.



C-1

Instrument Setting

Exit

Mode Selection

☒ ASTM

☐ ISO

System Setting

Screen Light

Language

English

Factory Reset

Screen Rotation

Wifi Setting

Timezone Setting

Previous

Next

1/5

C-2

14

Parameter Setting

Exit

Illuminant&Angle

(The second illuminant is for calculating the metamerism)

First

C

2°

Second

A

2°

CMC(l:c)

l

2.0

c

1.0

CIE94

KL

1.0

KC

1.0

KH

1.0

CIE 2000

KL

1.0

KC

1.0

KH

1.0

Previous

Next

2/5

C-3

Tolerance Setting

Exit

Haze/T

CIE LAB&LCH

Hunter Lab

CIEDE2000

CIE LUV

CMC(l:c)&CIE94

Liquid

Temperature&Humi
dity

Haze/T

		Greater than	Less than	Between
dh(Haze) : ±	2.0	Fail	Fail	Pass
dt(T) : ±	2.0	Fail	Fail	Pass
dC : ±	2.0	Fail	Fail	Pass

3/5

Previous

Next

C-4

Other Settings

Exit

Average

☒ Single Test ☐ Average Test

Save Setting

☒ Manual Save ☐ Auto Save

Naming Rules

Target + ☒ Number + ☐ Date

Sample + ☒ Number + ☐ Date

4/5

Previous


Next

C-5

Display Setting

- H/T/C
- Haze/T**
- Haze
- Transmittance
- Clarity
- Color Diff.
- Data
- Figure
- Metamerism
- Liquid

5/5



Previous

Finish

C-6


[Calibration]

D-1

0% calibration

Perform 0% calibration according to the software prompt. In the ASTM mode, please cover the compensation port (comp-port) with the compensation port cap; in ISO mode, please keep the compensation port (comp-port) open.


This page can be used to set the calibration time. The default calibration valid time is 8 hours.



D-1


100% calibration

Perform 100% calibration as prompted by the software.

 Calibrate

ASTM C/2°

Valid Time 8 Hours



Step Two

100%

Keep haze-port aligned with the air and click the measurement button for calibration.


0% calibration succeed

Calibrate


D-3

Clarity calibration

Perform clarity calibration as prompted by the software.

 Calibrate ASTM C/2°

Valid Time 8 Hours ▾



Step Three

Clarity Adjust

Please place the calibration sheet on the clarity-port and click the measurement button to calibrate the clarity

100% calibration succeed

Calibrate

D-3


[Measure]

The measurement is divided into three modes: standard sample measurement, sample measurement and other measurement modes (metamorphism, liquid color)

E-1

Standard measurement

Click Measure on the homepage to enter the standard sample measurement interface. After the sample is placed, click the measurement button in the lower right corner of the screen. The measurement data is displayed on the screen. The measurement button returns to the pressable state, indicating that the measurement is complete.




Click to measure

E-1

Sample measurement

In the standard sample measurement interface, click the sample measurement on the interface to switch to the sample measurement interface. Similarly, after the sample is placed, click the measurement button in the lower right corner of the screen to perform sample data measurement.



[Setup]


The setting interface can configure the instrument measurement method, data calculation parameters, tolerance, software display, saving method, naming rules, average, etc. After modification, you need to click the "Apply" button.

F-1

Instrument settings

The instrument settings are divided into 6 areas:

1. Haze measurement mode: ASTM mode or ISO mode can be set;
2. System settings: You can set the screen backlight and language switch;
3. Factory reset: software configuration is restored to the initial state;
4. Screen rotation: Click on the screen to rotate the screen and the color will reverse 180°;
5. Wifi settings: you can choose WiFi and log in;
6. Time zone setting: time display in different countries, network can automatically synchronize time.



F-2

Parameter settings

Parameter setting can configure the data calculation

1. Light source & angle: You can set the light source and angle of the calculated data. The first light source and angle are the calculated data in all modes, and the second light source is only used to calculate the metamerism (Note: the data of the similar color search display is fixed at D65/ 10°)

- 2、CMC(l:c):L:c coefficient of CMC color difference formula can be set;
- 3、CIE 94:Can set KL, KC, KH coefficients of CIE94 color difference formula;
- 4、CIE 2000:Can set KL, KC, KH coefficients of CIE2000 color difference formula;

Setting ASTM C/2°

Instrument **Parameter** Tolerance Display Other Guide Apply

Illuminant&Angle (The second illuminant is for calculating the metamerism)

First C 2°

Second A 2°

CMC(l:c)

l 2.0 c 1.0

CIE94

KL 1.0 KC 1.0 KH 1.0


CIE 2000

KL 1.0 KC 1.0 KH 1.0

F-2

Tolerance settings


Tolerance is used to judge whether the measurement data is qualified. When the measurement data exceeds the tolerance range, the data will be disqualified. When the measurement data is less than or equal to the tolerance, the data will be prompted to be qualified. In this interface, you can set the tolerance of different color difference formulas and modes. (Where CIE LAB can customize the prompt language)



Display setting

Display settings can set the content displayed under "Measurement Page". Divided into the following:

1. Haze/transmittance/sharpness: display haze, total transmittance and sharpness parameters at the same time;
2. Haze/transmittance: Simultaneously display the parameters of haze and total transmittance;
3. Haze: Only display haze parameters;
4. Transmittance: Only the total transmittance parameter is displayed;
5. Clarity: only display the clarity parameter;
5. Color difference: CIELABCH, CIEDE2000, CIE94, CMC, HunterLab;
6. Data: This mode can display all parameters that can be measured by the instrument except haze and hiding power;
7. Image: CIE LAB diagram, Yxy diagram, Luv diagram, reflection/transmittance diagram, K/S curve diagram, absorbance curve diagram;
9. Metamerism: measure metamerism parameters;
10. Liquid color: measure saybolt, ASTM color, platinum-cobalt color, Gander color;



F-6

Other settings

1. The average setting window can set single measurement or average measurement;
2. The save setting window can be set to save manually or automatically;
3. The naming rule window can set the naming rule when the standard sample is saved.

The screenshot shows a software interface for settings. At the top, there's a 'Setting' title bar with a home icon on the left and 'ASTM C/2°' on the right. Below the title bar are several tabs: 'Instrument', 'Parameter', 'Tolerance', 'Display', 'Other' (which is selected), 'Guide', and 'Apply'. The 'Other' tab contains three main sections: 'Average', 'Save Setting', and 'Naming Rules'. The 'Average' section has two radio buttons: 'Single Test' (selected) and 'Average Test'. The 'Save Setting' section has two radio buttons: 'Manual Save' (selected) and 'Auto Save'. The 'Naming Rules' section contains two rows. The first row is for 'Target' and the second for 'Sample'. Each row has a text input field (containing 'Target' and 'Sample' respectively), followed by a '+' sign, a checked 'Number' checkbox, another '+' sign, and an unchecked 'Date' checkbox.

F-6

[Data browsing]

G

1. The left side of the page shows the standard sample data list, and the right side shows the sample data list under the standard sample;
2. There is a search box on the left side of the page, click to search the target data;
3. After clicking one of the standard samples, you can see the detailed information of the sample data under the standard sample data on the right side of the interface;
4. Long press the standard sample or sample to choose to recall, modify, delete the current selection, delete all;
5. Click the standard sample to enter the sample detailed information interface, you can search for the sample under the current standard sample, and you can export the current display data;
6. Click Parameter Edit to pop up the parameter editing window, where you can select the parameters displayed on the data interface.

Standard search box

Standard data list

Home

Data View

ASTM C/2°

Target Search

Target0001

Edit

	Name	L*	a*	b*	dE*ab	P/F dB
Target	Target0001	99.99	-0.09	-0.06	--	--

Test Search

Name ▾

Search

Export

Export All

G-1

Home

Data View

ASTM C/2°

Target Search

Target0002

Target0001

Edit	Name	L*	a*	b*	dE*ab	P/F dB
Target	Target0002	99.99	-0.06	-0.08	--	--
0	Sample0001	100.01	-0.05	-0.13	0.05	Pas

Test Search

Name ▾

Search

Export

Export All

Sample data list

Can export the current display data and export all data

G-2

Data View

ASTM C/2°

Target Search

Target0002

Target0001

Edit

	Name	L*	a*	b*	dE*ab	P/F dE
Target	Target0002	99.99	-0.06	-0.08	--	--
0	Sample0001	100.01	-0.05	-0.13	0.05	Pas

Set Into Target

Revise

Delete Selected

Delete All

Test Search

Name

Search

Export

Export All



[Personal center]

H-1


The personal center interface can modify the account password and cancel the current account.

The screenshot displays a web interface titled "Individual Center" with a dark header bar. On the right side of the header, the text "ASTM C/2°" is visible. The main content area is divided into two columns. The left column, titled "Account: admin", contains four input fields: "Company Name", "Address", "Contact Name", and "Email". The right column, titled "Change Password", contains three input fields: "Old Password", "New Password", and "New Password Confirm", followed by an "Enter" button. At the bottom right of the interface is a "Logout" button. A blue oval with the text "H-1" is positioned at the bottom right of the screenshot.

[About]

I-1

About the interface, you can view the instrument information, such as software version, instrument version, instrument serial number, instrument model, etc.



I-1

[Log]

J-1

On the log interface, you can see the instrument login information, calibration information, instrument error information, etc.


Daily Record		ASTM C/2°
2016-01-02 20:43:05.3	100% successful calibration of instrument	
2016-01-02 20:42:14.7	0% calibration succeed	
2016-01-02 20:39:30.2	Account Login admin	
2016-01-02 20:38:27.4	Account Login admin	
2016-01-02 20:36:12.8	100% successful calibration of instrument	
2016-01-02 20:35:56.4	0% calibration succeed	
2016-01-02 07:34:28.4	100% successful calibration of instrument	
2016-01-02 07:34:16.1	0% calibration succeed	
2016-01-02 07:30:36.6	100% successful calibration of instrument	
2016-01-02 07:30:23.9	0% calibration succeed	

J-1

[Update]

K-1

In the case of networking, you can click Update to detect whether there is new software to obtain the latest software.




K-1

Introduction to the measurement interface

[Haze/transmittance/Clarity]

L-1

In this interface, the haze, total transmittance, sharpness and transmittance curve (%) can be displayed at the same time, and the difference between haze, total transmittance and sharpness can be calculated by comparing the standard samples, and passed simultaneously. The set tolerance automatically judges whether the sample is qualified.




L-1

[Haze/transmittance]

M-1

In this interface, the haze, total transmittance and transmittance curve (%) can be displayed at the same time, the difference between haze and total transmittance is calculated by comparing the standard sample, and the tolerance is automatically set at the same time Determine whether the sample is qualified.




M-1

[Haze]

M-1

In this interface, only the haze and transmittance curves (%) are displayed, and the difference in haze is calculated by comparing the standard sample, and at the same time, the sample is automatically judged by the set tolerance.




M-1

[Transmittance]

N-1

On this interface, only the total transmittance and transmittance curve (%) are displayed. The difference in total transmittance is calculated by comparing the standard sample, and the sample is automatically judged by the set tolerance.




N-1

[Clarity]

0-1

In this interface, only the clarity is displayed, the difference in sharpness is calculated by comparing the standard sample, and the sample is automatically judged by the set tolerance.



Clarity	
Target	100.00
Sample	100.00
Difference	0.00
Dudge	Pass

[Color difference]

P-1

CIELABCH

In this interface, the L^* , a^* , b^* , c^* , h values of the sample color can be measured, and the dL^* , da^* , db^* , dc^* , dH^* , dE^*_{ab} are calculated by comparing with the standard sample. At the same time, automatically determine whether the sample is qualified by the set tolerance.

ASTM C/2°

Test Target --- Target0003

Test Sample --- Sample0001

Target	Sample	
L* = 18.87	L* = 19.03	dL* = 0.15 Pass
a* = 18.46	a* = 18.56	da* = 0.10 Pass
b* = 18.03	b* = 17.25	db* = -0.78 Pass
c* = 25.81	c* = 25.34	dc* = -0.47 Pass
h = 44.34	h = 42.91	dH* = -0.64 Pass
		dE*ab 0.81 Pass

Setting

Save

Measure

P-1

P-2

CIEDE2000

In this interface, the L^* , a^* , b^* , c^* , h values of the sample color can be measured, and the dL' , dC' , dH' , and dE^*2000 can be displayed by comparing with the standard sample calculation, and at the same time through the setting The tolerance of automatically determines whether the sample is qualified.

The interface displays color measurement data for a Target (Target0003) and a Sample (Sample0001). It includes a table of colorimetric values, a summary of differences, and a final dE^*2000 result with a Pass/Fail status. A sidebar on the right contains icons for Setting, Save, and Measure.

Target	Sample
$L^* = 18.50$	$L^* = 18.20$
$a^* = 17.92$	$a^* = 17.72$
$b^* = 17.08$	$b^* = 16.38$
$c^* = 24.76$	$c^* = 24.13$
$h = 43.63$	$h = 42.76$

$dL' = -0.30$	Pass
$dC' = -0.62$	Pass
$dH' = -0.40$	Pass

dE^*2000 0.47 Pass

P-2

P-3

CIE94

In this interface, the L^* , a^* , b^* , c^* , h values of the sample color can be measured, and the dL^* , da^* , db^* , dc^* , dH^* , and dE^* are calculated by comparing with the standard sample. 94. At the same time, it automatically judges whether the sample is qualified by the set tolerance.

ASTM C/2°

Test Target --- Target0003

Test Sample --- Sample0001

Target	Sample	
$L^* = 18.10$	$L^* = 17.79$	$dL^* = -0.31$ Pass
$a^* = 17.98$	$a^* = 17.66$	$da^* = -0.32$ Pass
$b^* = 16.59$	$b^* = 15.99$	$db^* = -0.60$ Pass
$c^* = 24.47$	$c^* = 23.82$	$dc^* = -0.64$ Pass
$h = 42.70$	$h = 42.16$	$dH^* = -0.23$ Pass
		dE^*_{94} 0.46 Pass

Setting


Save

Measure

P-4

CMC

In this interface, the L^* , a^* , b^* , c^* , h values of the sample color can be measured, and the dL^* , da^* , db^* , dc^* , dH^* , and $dE_{cmc}(l:c)$, at the same time automatically determine whether the sample is qualified by the set tolerance.



Hunter Lab

In this interface, the values of Hunter L, Hunter a, and Hunter b of the sample color can be measured, and dHunter L, dHunter a, dHunter b, and dEab can be calculated by comparing with the standard sample. At the same time, whether the data is automatically determined by the set tolerance qualified.

ASTM C/2°

Test Target --- Target0003

Test Sample --- Sample0001

Target	Sample	
(Hunter)	(Hunter)	
L = 15.99	L = 15.92	dL = -0.07 Pass
a = 11.51	a = 11.51	da = -0.00 Pass
b = 7.24	b = 7.23	db = -0.00 Pass
		dEab 0.07 Pass

Setting

Save

Measure

[Data]

Q-1

1. In the data interface, you can click parameter edit to select the parameter you want to see;
2. Check the parameter difference of the sample by measuring the standard sample and then measuring the sample;
3. Click on the data to select it, and long press on the data to delete and rename the data.


ASTM C/2°						
Test Target						
Test Sample						
Edit	Name	L*	a*	b*	dE*ab	P/F dE*ab
Target	Target0003	19.20	18.68	17.05	--	--
1	Sample0001	18.88	18.68	17.27	0.39	Pass

[Figure]

R-1

CIELAB


In this interface, you can measure the L^* , a^* , and b^* values of the sample, and at the same time use the a^* and b^* values of the sample to trace points on the CIELAB graph and display the L^* , a^* , and b^* values of the data.



R-2

Yxy

In this interface, you can measure the Y, x, and y values of the sample, and use the x and y values of the sample to trace points on the Yxy graph and display the Y, x, and y values of the data.




R-2

R-3

Luv


In this interface, you can measure the L^* , u^* , and v^* values of the sample, and use the u' and v' values of the sample to trace points on the Luv chart and display the L^* , u^* , and v^* values of the data.



R-4

k/s curve


In this interface, the k/s value of the sample can be measured, and the K/S curve under 360-780nm is displayed at the same time.



R-4


Transmittance curve

In this interface, the transmittance value of the sample can be measured, and the transmittance curve under 360-780nm can be displayed.



Absorbance curve


In this interface, the absorbance value of the sample can be measured, and at the same time, the absorbance curve under 360-780nm can be displayed.



[Metamerism]

S-1


The left side of the interface is the value calculated by the measurement sample using the first light source/angle, and the right side is the value calculated by the measurement sample using the second light source/angle. Metamerism values.



[Liquid color]

T-1

The cuvette optical path on the left of the interface is the recommended cuvette optical path size for measuring different parameters (for example, if you want to measure the saybolt parameter, the recommended cuvette optical path size at this time is 50mm), the right is the parameter value, and whether it is qualified Judgment.



Cuvette Light Path	Parameter	Target	Sample	Difference	Dudge
10mm	Pt-Co/Hazen/ APHA	500.00	500.00	0.00	Pass
10mm	Gardner Color	13.91	13.87	-0.04	Pass
50mm	Saybolt	-16	-16	0	Pass
33mm	ASTM Color	4.6	4.6	-0.0	Pass

T-1

Parameter introduction


Haze

Diffuse scattering reduces the image quality of the object. Small particles inside the material or sample surfaces cause scattering, and scattered light is scattered to different angles and the optical density at each angle is small. It causes a decrease in contrast and the sample forms a milky or cloud-like appearance, this phenomenon is known as haze.

Conditions for the assessment of transparency



Transparent product appearance has the characteristics of gloss, color and transparency. Transparency is particularly important, and its evaluation conditions are: transmittance, haze and so on. The ratio of light to incident light when the transparency rate is all projected. It will decrease as the surface of the material reflects and absorbs light. According to the ASTM D1003 the percentage of light that when passing through that deviates from the incident beam by greater than 2.5 degrees on average is defined as haze.

Measuring principle




When a beam of parallel light hits the sample and enters the integrating sphere, it is scattered on the sphere inner white coating, the total transmittance is measured when the optical trap outlet on the sphere is closed. When the optical trap is opened, haze will be measured.

Compensation method



The above picture is not using the compensation method to measure the transmission rate, in two times measurement, because the integral sphere's area is different, causes the integral sphere efficiency are different, thus has the certain influence to the measurement result accuracy.




The above picture is used to measure the transmission rate by the compensation method, a compensating port is added to the integral sphere, the first measurement sample is placed at the compensation port, the second measurement sample is placed at the measuring port, while the compensation port is in the open state, the integral sphere area of the two measuring process is identical, the integral sphere is consistent, so that the measurement result is more accurate.

Exception handling analysis


Error	Analysis	How to solve?
1.The instrument does not start.	Power connection may be abnormal	Check the Power interface for good contact and plug in the power supply.
2.No access to main interface after start.	The power-on calibration process may be abnormal	Re-calibrate as required
3.Error in measurement results.	Tolerance settings may be abnormal	Check tolerance settings and adjust
4.Test result is not correct	1.The sample is close to the test port or not 2.Whether the sample surface is with scratches	1.Check the sample and test port fit to ensure close fitting 2.Check the sample surface condition to ensure that the sample is at good condition and has no effect on the measurement.

Annex


Standard accessories




Power Adapter




USB Cable



PC Software CD




Compensation Port Cover




0% Calibration Cover

Select Accessories



Film Sample Fixture



Liquid Sample Fixture

Company statement

- Our company commits to our customers 1 year warranty period for our Haze Meter series products from the date of the purchase, and our company shall be responsible to provide free maintenance for non-human caused malfunctions under normal usage. For malfunctions that are out of warranty period or caused by human factors, the company shall provide maintenance, and materials and repair shall be chargeable.
- The company is not liable for any loss or claim arising from the use of this product by the third party.
- The company is not liable for any damage caused by loss of data due to failure, maintenance or power off. To prevent the loss of critical data, be sure to back up all your data.
- The copyright of all products preset in this product belongs to the company and is protected by copyright law of the People's Republic of China.
- Our company's sale of this product does not represent the transfer or grant of any rights related to the copyright of the works, to the user.
- The product specifications and information mentioned in this specification are for reference only and will be updated at any time without prior notice.